









# Hulten.no

## CRT Wear & Burn Examples

Rating	Description	Action	
1	New or mint - great condition	None	
2	Light usage - faint signs of wear.	N/A	
3	Low usage - slightly heavier definition of previous display on face of tube.	N/A unless projector is changed from 4:3 to 16:9. In this case, the uneven wear will show whites as slightly yellow.	
4	Moderate usage - Browning or burn on the face of the tubes readily identifiable. Color balance may become an issue.	N/A unless projector is changed from 4:3 to 16:9. In this case, the uneven wear will show whites as yellow in an uneven pattern.	

5	Medium usage - Browning is fairly obvious and you are starting to wonder why blue skies tend to be gray.	It's time to start pricing used tubes depending upon how many hours you put on your projector. With infrequent use, these tubes will last a long time.	
6	Burn	Should be replaced.	
7	Heavy Burn	Should be replaced.	
8	Very Heavy Burn	Should be replaced.	
9	Computer Burn	Should be replaced.	